# Cam screws with hexagon washer



#### Item description/product images



# Description

Material: Cam screw carbon steel. Hex washer brass.

#### Version:

Cam screw tempered to 10.9 and black oxidised.

### Note:

The minimal height of this fixture clamp enables numerous clamping problems in fixture and equipment construction to be solved. The brass hex washer offers a gentle yet extremely stable and safe clamping of workpieces. By using several fixture clamps entire pallets can be set-up.

Clockwise rotation is recommended for clamping. The hex socket on the screw should be on the right after tightening. (Screw in the cam screw as far as it will go, then turn it back one turn).

"A" = distance from workpiece to screw centre (cam screw).

### Assembly:

Clamping method:

- 1. Screw the cam screw in as far as it will go.
- 2. Screw the cam screw back one turn.
- 3. Position the workpiece.

4. Turn the cam screw clockwise to clamp the workpiece. (The hex socket on the cam screw should now be on the right).


#### **On request:**

Replacement screw for cam screws K1969

# Cam screws with hexagon washer



Drawings



#### **Overview of items**

# Cam screws with hexagon washer

Order No.	A	D	Н	L	SW	SW1	S1 (travel)	Clamping force kN	Tightening torque max. Nm	Accessories KIPP
K0026.04	3,8	M4	2,8	10	8	3	0,76	0,91	2	K1969.0410
K0026.06	7,8	M6	4,8	12	16	4	1,01	3,56	8,5	K1969.0612
K0026.08	10,2	M8	4,8	15	20,6	5	1,01	3,56	11,3	K1969.0815
K0026.10	10,2	M10	6,4	20	20,6	7	1,27	8,89	28	K1969.1020
K0026.12	12,7	M12	9,5	25	25,4	8	2,03	17,79	88	K1969.1225
K0026.16	15	M16	12,7	30	30,2	12	2,54	26,68	125	K1969.1630